



# IECEX CoC Certified Service Facility

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit [www.iecex.com](http://www.iecex.com)

Certificate No.: **IECEX SIR S0032** Page 1 of 1 [Certificate history:](#)  
Status: **Current** Issue No: 0 [Issue 0 \(2021-04-09\)](#)  
Date of Issue: 2021-04-09  
Applicant: **Matric Limited**  
2099 Hill City Road  
Seneca  
PA 16346  
USA  
**United States of America**  
Type of Service: **Repair and Overhaul according to IEC 60079-19**  
Type of Protection: **Intrinsic Safety "i"**  
Scope of Service: Repair and overhaul of Group 1 Mining Equipment

Locations covered by this Certificate:

**Matric Limited**  
2099 Hill City Road  
Seneca  
PA 16346  
USA  
**United States of America**

Facility Audit Report:

[GB/SIR/FAR21.0002/00](#)

*This certificate is issued as verification that the Service Facility and associated locations were assessed and found to comply with the IECEx Scheme requirements, relating to the type and scope of service listed above. This certificate is granted subject to the conditions as set out in IECEx Scheme Rules, IECEx 03 and Operational Documents as amended.*

Approved for issue on behalf of the IECEx  
Certification Body:

**Matthew Fielding**

Position:

**Audit Team Manager**

Signature:  
(for printed version)

Date:

**29/04/2021**

1. This certificate and schedule may only be reproduced in full.
2. This certificate is not transferable and remains the property of the issuing body.
3. The Status and authenticity of this certificate may be verified by visiting [www.iecex.com](http://www.iecex.com) or use of this QR Code.



Certificate issued by:

**SIRA Certification Service**  
**CSA Group**  
**Unit 6, Hawarden Industrial Park**  
**Hawarden, Deeside, CH5 3US**  
**United Kingdom**

**sira**  
CERTIFICATION

